SIZE

SAME

ОF

COUNTY Workston

TOWN Girdletree VICINITY

STREET NO. Borrion Rd, I mile North y
Hudson Rd. (Rot)

ORIGINAL OWNER

ORIGINAL USE dwelling

PRESENT OWNER John Timmons

PRESENT USE tenant

WALL CONSTRUCTION brick + frame

NO. OF STORIES 1+2

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY

WO-50

2. NAME John Timmons Formhouse

DATE OR PERIOD C. 1800 STYLE Commit costage ARCHITECT BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC INO

The Timmons farmhouse has two parts, one is a one-story section with (knee walls), being two bays long of brick laid in common bond and having two chimneys partly projecting from the wall and joining at the 2nd story to form one chimney as it goes out the roof. The upper part is rebuilt with new brick. In the gable are two windows with six over six sash and one door on first story, access to which is by several concrete steps. The other sides of this section are built of frame covered with asbestos shingle. There are two windows with nine over six sash on each side. The original box cornice is in place as are three of the curved end-boards, typical of Worcester County houses.

On the northeast side is a two-bay wing of the late nineteenth century with four over four sash, asbestos siding.

5. PHYSICAL CONDITION OF STRUCTURE Endangered 100

(n

Exterior

0000

an "A" roof and one brick chimney on its gable. It is narrower than the older section and stands about four feet taller.

It is in very poor condition and is tenanted. Two corn cribs and two other outbuildings of little interest stand near

the dwelling.

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH
9. NAME, ADDRESS AND TITLE OF RECORDER

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

Michael Bourve Maryland Historical Trust

DATE OF RECORD OCT, 1969



John Timmous House WO-50